

Farmington 0416



Bridge Name and Number :	WEBSTER Farmington 0416
Feature Carried :	Webster Road
Feature Crossed :	Wilson Stream
Latitude :	44° 37' 17.2"
Longitude :	70° 08' 46"

CHA Consulting Inc has been retained by the MaineDOT to evaluate scour/erosion issues at many bridges throughout the state of Maine. Ben Foster, PE is our direct contact and he works under John Buxton, PE (MaineDOT Bridge Maintenance Engineer). For these state and locally owned bridges, no plans were found in the DOT files in Augusta, Me. Your assistance in providing any original and/or rehabilitated plans (especially soil borings) would be helpful.

Summary of Facts:

Town/City Clerk: Leanne Pinkham
 Address: 153 Farmington Falls Rd
 Farmington, Maine 04938
 Telephone: (207) 778-6539
 Email: townclk@farmington-maine.org
 Fax: (207) 778-5871

Public Works Director: Denis Castonguay
 Address:
 Telephone: (207) 778-2191 Fax:
 Email: publicworks@farmingtonmaine.org
 Contact date:

Note:

County: Franklin Bridge Location: 0.6 mile South Knowlton Corner Rd
 Year built: 1950 Reconstructed? Yes X No If yes, when? 2003
 Bridge Plans on file? Yes No If yes/ pages?
 Type of Plans on file: Original Rehabilitated, Date: Other:

Is Municipality willing to send CHA copies of bridge plans via:

Email Hardcopy by mail Other:

Mailing Address to: c/o Bob Stomski, CHA Consulting, Inc. 11 King Court, Keene, NH 03431
 Email to: rstomski@chacompanies.com